I_{PN}= 2000 A

Measureable currents are AC, DC, pulsed …

Identification	Part numbered	Drawing	Dimensions in mm
HCSR 2000 Sensor fastening: 4 x M6 Steel screws (recommended fastening torque 4.2 Nm) Tolerances ±0.5 mm			
HCSR 2000 Connections: Screw terminal with faston; 4pins Screen connected to separate terminal	**20 31 200 9101**		
HCSR 2000 including shielded cable 1000 mm 0.5 mm², stripped with end sleeve 1 - (numbereded white strands) 2 M 3 + Internal screen on separate terminal Other secondary connections on request	**20 31 200 9201**	Sensor with separate cable